

**CAUTION:** There should be no continuity between the negative cable from the roof and the negative cable from the charge controller. If they connect it will fail. Keep these isolated from each other.





## NOTICE:

The "greyed out" battery bank items are not included, but you will be interacting with them.

olar












normal. Scan here for assistance. 5 AM Solar Inc. 3555 Marcola Rd. Springfield, OR 97477 541.726.1091 www.amsolar.com



AM Solar Inc. 3555 Marcola Rd. Springfield, OR 97477 541.726.1091 www.amsolar.com

CABLE OUTPUT INSTALLATION VIDEO

1

ROCKER FOOT MOUNT

2

3

SOLAR PANEL INSTALLATION VIDEO

ROOF COMBINER BOX INSTALLATION VIDEO 4



5