


CAUTION:

There should be no continuity between the negative cable from the roof and the negative cable from the charge controller. If they connect it will fail. Keep these isolated from each other.



NOTICE:

The "greyed out" battery bank items are not included, but you will be interacting with them.







